

CORRECTIVE ACTION REPSONSE

DOCUMENT NUMBER: 713400261
FACILITY NAME: SKINNER RIDGE 36-BV
Location: CHEVRON USA INC SKR-65S98W/36NWSW
Location ID: 336048

CORRECTIVE ACTION #1 COMMENT:

Tank missing labeling. Tank in tank battery is missing name of operator, operators emergency contact information, tank capacity and tank contents.

CORRECTIVE ACTION RESPONSE:

Labels have been added to tank - 09/04/2024



CORRECTIVE ACTION #2 COMMENT: Chemical tank has no labeling.


CORRECTIVE ACTION RESPONSE: Labels have been added to tank - 09/09/2024



CORRECTIVE ACTION #3 COMMENT:
Multiple debris on location, refer to photos.

CORRECTIVE ACTION RESPONSE:

On the day of the receipt of this inspection report (28 August 2024) and corrective actions noted the Skinner Ridge Well Pad 36-BV was gone over by Chevron crews and all debris was removed from the pad and properly disposed of.





CORRECTIVE ACTION #4 COMMENT:

Multiple open ended piping/wildlife hazard/ available for entry by wildlife.

CORRECTIVE ACTION RESPONSE:

Piping was unhooked to allow P&A rig to move to next well in operation and then reconnected - 08/29/2024.




CORRECTIVE ACTION #5 COMMENT:
Separator doors open/wildlife hazard.

CORRECTIVE ACTION RESPONSE:
Separator doors have been closed - 08/28/2024.



CORRECTIVE ACTION #6 COMMENT:
PRV does not comply with CECMC pressure safety device rules.

CORRECTIVE ACTION RESPONSE:
Both PRV lines were capped - 08/28/2024.



CORRECTIVE ACTION #7 COMMENT:
Stockpiled soils with no BMP's, refer to photos.

CORRECTIVE ACTION RESPONSE:
This stockpile was of clean dirt. It was removed and spread to fill low areas on location. -
09/05/2024

