

Inspection Photos

Location Name: CAERUS PICEANCE LLC MCU 32-7 (G32E) Pad

Location #: 334140



Photo # 9006 From Entrance to location



Photo # 9007 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MCU 32-7 (G32E) Pad

Location #: 334140



Sep 6, 2024 at 1:37:37 PM

Photo # 9008 Location



Sep 6, 2024 at 1:35:00 PM
CO

Photo # 9009 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MCU 32-7 (G32E) Pad

Location #: 334140



Photo # 9010 Location



Photo # 9011 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MCU 32-7 (G32E) Pad

Location #: 334140



Photo # 9012 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 9013 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC MCU 32-7 (G32E) Pad

Location #: 334140



Photo # 9014 Multiple holes in liner/liner needs maintenance




Photo # 9015 Multiple holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC MCU 32-7 (G32E) Pad

Location #: 334140



Photo # 9016 Multiple holes in liner/liner needs maintenance



Photo # 9017 Multiple holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC MCU 32-7 (G32E) Pad

Location #: 334140



Photo # 9018 Label on methanol tank contains incorrect information/does not comply with CECMC rules




Photo # 9019 Label on methanol tank contains incorrect information/does not comply with CECMC rules