

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2024

Submitted Date:

09/09/2024

Document Number:

708904538

**FIELD INSPECTION FORM**

Loc ID 334140 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 26 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290305	WELL	PR	08/01/2017	GW	045-14084	MCU 32-7(G32E)	PR
290306	WELL	PR	08/01/2017	GW	045-14083	HMU 32-3 (G32E)	PR

**General Comment:**

[CECMC Inspection Report Summary](#)

On 09/06/2024 at approximately 13:33 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at CAERUS PICEANCE LLC MCU 32-7 (G32E) Pad. Location # 334140 in Garfield County Colorado. Location is within Black Bear Habitat area & in close proximity to High Priority/Density/NSO Habitat areas. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Rupture disc vent line does not comply with CECMC pressure safety device rules with a CA date of 09/16/2024
2. Tanks & Berms - Multiple holes in liner/liner needs maintenance with a CA date of 09/29/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead signs at separators		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Label on methanol tank contains incorrect information/does not comply with CECMC rules - please refer to photo log		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Small amount of weeds in secondary containment		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence		

Corrective Action:		Date:	
Type	OTHER		
Comment:	Pig station - pipe rail fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Rupture disc vent line on separator unit does not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	09/16/2024
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Pressure transducers located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gal
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				

Comment:		Centralized containment				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	300 BBLs	STEEL AST		,		
Comment:		Tanks equipped with telemetry				Date:	
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Inadequate	Walls Insufficient		Inadequate			
Comment:		Multiple holes in secondary containment liner/liner needs maintenance				Date:	
		Centralized containment					
Corrective Action:		The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.				Date: 09/29/2024	
<b>Venting:</b>							
Yes/No	NO						
Comment:							
Corrective Action:							
						Date:	
<b>Flaring:</b>							
Type							
Comment:							
Corrective Action:							
						Date:	

**Inspected Facilities**

Facility ID: 290305 Type: WELL API Number: 045-14084 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290306 Type: WELL API Number: 045-14083 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction
		Ditches				
Gravel						Sparse to none in areas
Retention Ponds						
		Compaction				Small amount of light compaction
		Culverts				
Other						Small amount of erosion on slope behind battery
		Other				Mag chloride on some sections of lease road
		Gravel				Sparse to none in sections

Comment:

Corrective Action:

Date:

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Please refer to Equipment & Tanks & Berms for corrective actions & refer to Signs/Marker & Stormwater for comments.	smelserw	09/09/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904539	Inspection 708904538 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6699168">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6699168</a>
708904540	Inspection 708904538 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6699169">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6699169</a>