



FORM  
INSP  
  
Rev  
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
09/05/2024  
Submitted Date:  
09/10/2024  
Document Number:  
708302714

FIELD INSPECTION FORM

Loc ID  
334826

Inspector Name:  
Morris, Matthew

On-Site Inspection ☐

2A Doc Num:

Operator Information:

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☒ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211075	WELL	PR	09/07/2001	CBM	045-06833	DOE 1-M-31	PR
260367	WELL	PR	05/07/2002	GW	045-07849	FEDERAL PA 23-31	PR
292999	WELL	PR	10/31/2008	GW	045-14832	FEDERAL PA 524-31	PR
293002	WELL	PR	10/30/2008	GW	045-14834	FEDERAL PA 423-31	PR
293019	WELL	PR	10/31/2008	GW	045-14835	FEDERAL PA 314-31	PR
293020	WELL	PR	10/31/2008	GW	045-14836	FEDERAL PA 413-31	PR
293021	WELL	PR	10/31/2008	GW	045-14837	FEDERAL PA 313-31	PR
293022	WELL	PR	10/31/2008	GW	045-14838	FEDERAL PA 534-31	PR
293030	WELL	PR	10/27/2008	GW	045-14839	FEDERAL PA 522-31	PR
293032	WELL	PR	10/31/2008	GW	045-14831	FEDERAL PA 434-31	PR
293037	WELL	PR	10/31/2008	GW	045-14830	FEDERAL PA 414-31	PR
293110	WELL	PR	10/27/2008	GW	045-14891	FEDERAL PA 323-31	PR

General Comment:

CECMC Inspection Report Summary

On 9/5/2024 at approximately 11:50, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW at Location ID #334826 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) General safety; open wellhead cellars

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Date Run: 9/10/2024 Doc [#708302714]

Page 1 of 7

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Open wellhead cellars on PA 23-31 and PA 13-31.		
Corrective Action:	Cover wellhead cellars. 602.c: Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.	Date:	08/08/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		

Corrective Action:			Date:		
<b>Equipment:</b>			corrective date		
Type: Ancillary equipment	# 1				
Comment: Liquid nitrogen tank					
Corrective Action:			Date:		
Type: Bradenhead	# 12				
Comment:					
Corrective Action:			Date:		
Type: Bird Protectors	# 8				
Comment:					
Corrective Action:			Date:		
Type: Plunger Lift	# 12				
Comment:					
Corrective Action:			Date:		
Type: Ancillary equipment	# 1				
Comment: CataFlow					
Corrective Action:			Date:		
Type: Gas Meter Run	# 14				
Comment:					
Corrective Action:			Date:		
Type: Horizontal Heated Separator	# 14				
Comment:					
Corrective Action:			Date:		

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:		Date:				
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	

Comment:					
Corrective Action:					Date: <input type="text"/>
<b><u>Paint</u></b>					
Condition	Adequate				
Other (Content)					<input type="text"/>
Other (Capacity)					<input type="text"/>
Other (Type)					<input type="text"/>
<b><u>Berms</u></b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date: <input type="text"/>
<b><u>Venting:</u></b>					
Yes/No	NO				<input type="text"/>
Comment:					<input type="text"/>
Corrective Action:					Date: <input type="text"/>
<b><u>Flaring:</u></b>					
Type					<input type="text"/>
Comment:					
Corrective Action:					Date: <input type="text"/>

Inspected Facilities						
Facility ID:	211075	Type:	WELL	API Number: 045-06833	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	260367	Type:	WELL	API Number: 045-07849	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	292999	Type:	WELL	API Number: 045-14832	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	293002	Type:	WELL	API Number: 045-14834	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	293019	Type:	WELL	API Number: 045-14835	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	293020	Type:	WELL	API Number: 045-14836	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	293021	Type:	WELL	API Number: 045-14837	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	293022	Type:	WELL	API Number: 045-14838	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293030	Type:	WELL	API Number:	045-14839	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293032	Type:	WELL	API Number:	045-14831	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293037	Type:	WELL	API Number:	045-14830	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293110	Type:	WELL	API Number:	045-14891	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
Sediment Traps						
Rip Rap						
		Compaction				
		Sediment Traps				
		Rip Rap				
Gravel						
		Tracking Pad				
		Check Dams				
Compaction						
		Culverts				
		Ditches				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302715	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6699684">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6699684</a>