

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Noxious weed growth



Well sign missing required information

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Debris



Debris

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Stack missing bird protection



Stack missing bird protection

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Debris



Oily waste and staining

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Oily waste and staining



Stack missing bird protection

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Stack missing bird protection



Relief risers missing protective caps

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Debris



Open ended loadline

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Soil staining



Soil staining

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Tank battery sign missing required information

Location from Northwest corner

**Antler Energy LLC
Pole Gulch 6
Location ID: 312865**



Location from Southeast corner



Location from Southwest corner