

Operator: CPR

Location Name: CHAVEZ 61N65W / 4 SWSE HZ PAD

Loc ID: 428697

Inspection: 708201513







CA: This location does not comply with Rule 1003. It was observed that the disturbance area has been reduced for areas only need for production operations, however, undesirable vegetation (kochia and Russian thistle) was observed throughout the disturbance areas. The southern interim areas do not appear to be progressing towards reclamation standards and regulations with little evidence of desirable perennial vegetation observed. The northern portion appears to have been converted into cropland with poor crop growth observed. Refer to attached inspection photos. Perform reclamation in accordance with Rule 1003.

CA Resolution: Operator has reported that the identified disturbed areas have been appropriately addressed and seeded. The location has also been mowed and weeds removed.

CA: This location does not comply with Rule 1002.f. During this inspection it was observed that the production areas are experiencing erosion degradation (e.g riling) with off location sediment transport observed in the interim areas. Additional stormwater repairs and/or implementation of additional control measures required. Refer to attached inspection photos. Comply with Rule 1002.f.

CA Resolution: Operator has reported that identified areas of erosion have been appropriately repaired to comply with Rule 1002.f.