

Inspection Photos

08/22/2024

Operator: PETROLEUM RESOURCE
MANAGEMENT CORP - 10421

Location ID: 436485

Inspection Doc: 696206212

Moffat County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PETROLEUM RESOURCE MANAGEMENT CORP - 10421

Location ID: 436485



Photo 1: Photos examples showing unused riser equipment remains on the Location. Risers require removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PETROLEUM RESOURCE MANAGEMENT CORP - 10421

Location ID: 436485



Photo 2: Photos taken from the cut slope on the south end of the Location. Photos show cutting materials remain stored on the Location, and that containment measures to prevent the E&P waste from migrating off-site, as well as from impacting stormwater runoff, and surface water have not been implemented.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PETROLEUM RESOURCE MANAGEMENT CORP - 10421

Location ID: 436485



Photo 3: Photos taken from the east end of the Location. Outlets on the north and east end of the Location have not been installed or maintained per good engineering practice; geotextile lining in conjunction with multiangular rip-rap material has not been implemented per good engineering practice; stormwater degradation to the walls of the outlets has persisted.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PETROLEUM RESOURCE MANAGEMENT CORP - 10421

Location ID: 436485



Photo 4: Photo example showing anchors on Location remain unmarked.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PETROLEUM RESOURCE MANAGEMENT CORP - 10421

Location ID: 436485



Photo 5: Photo taken from the fill slopes. Slopes on the north end of the Location remain predominantly bare; Operator has since stacked a 2nd erosion log on top of the wattles previously placed, however, BMPs to minimize erosion and degradation at the slope not been implemented.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PETROLEUM RESOURCE MANAGEMENT CORP - 10421

Location ID: 436485



Photo 6: Photos 6-8 example showing Noxious weeds have continued to establish and spread on Location; Canada thistle (seen in photo) have matured on the Location, and was in the process of seeding out at time of inspection. Weeds observed through the Cut and Fill slopes of the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PETROLEUM RESOURCE MANAGEMENT CORP - 10421

Location ID: 436485



Photo 7: See comments under photo 6. Vegetation in photo with “white top” is Canada thistle, the white material are the plants seeds that were dispersing at time of inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PETROLEUM RESOURCE MANAGEMENT CORP - 10421

Location ID: 436485



Photo 8: See comments under photo 6. Vegetation in photo with “white top” is Canada thistle, the white material are the plants seeds that were dispersing at time of inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources