

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2024

Submitted Date:

09/06/2024

Document Number:

715200822

FIELD INSPECTION FORM

Loc ID 333700 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments
1 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General	713-209-4000	FarmingtonRegulatoryTechs@hilcorp.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286247	WELL	PR	10/01/2009	CBM	067-09232	SCHIRARD 4-12U	PR

General Comment:

[SE Compliance Specialist Brian Welsh](#) conducted a routine field inspection of the well location and equipment

Location			
Lease Road:			
Type	Access		
comment:	Elevated gravel road through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sticker on separator. Sign mounted to fence at water tank. Stencil with capacity on tank hatch		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease signs at edge of location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Counterweights neatly store on base of pumping unit		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Wire panels around buried water tank		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Metal panels around separator and meter run		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Metal panels around pumping unit and wellhead		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 4		corrective date
Comment:	Electric panel, telemetry equipment at separator, control panel and phase convertor on north side of wellhead		

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:	1-Vertical heated separator for Schirard 4-12U on southwest side of location. 1-Vertical heated separator with metal shed on west side of location with built in liquid storage		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	Lufkin 320 for Schirard 4-12U. American 320 for Schirard 3-12U		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric motors		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access for both wells		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Not all deadmen are marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	09/27/2024
Type: Bird Protectors	# 2		
Comment:	Bird protectors on separator stacks		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Skid mounted compressor in metal shed on northwest corner of location		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	1-Meter run on southwest edge of location for the Schirard 4-12U. Calibration shows 8/16/24 1-Meter run in metal separator shed for the Schirard 3-12U. Calibration shows 8/20/24		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.206570,-107.662970
Comment:	120bbl buried steel open top water tank on north side of location next to compressor shed. Tank has metal wildlife protection				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	120bbbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Buried square metal containment with berms at ground level	Date:	
Corrective Action:			

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
067-09232		
067-08341		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 286247 Type: WELL API Number: 067-09232 Status: PR Insp. Status: PR

Producing Well

Comment: Well is PR at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/10/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Gravel	Pass					
Culverts	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403912344	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695891