

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
09/12/2024
Submitted Date:
09/12/2024
Document Number:
695110249

FIELD INSPECTION FORM

Loc ID 429093 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:
ECMC Operator Number: 10412
Name of Operator: AUSCO PETROLEUM INC
Address: 113 N SANTA FE AVENUE
City: FLORENCE State: CO Zip: 81226

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
17 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hart, Tim		thart@fremontpetroleum.com	All inspections
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@fremontpetroleum.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429092	WELL	WO	08/20/2018	LO	043-06216	Pathfinder 1	WO
430103	WELL	PR	06/01/2024	GW	043-06221	Pathfinder 2	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 22: UNUSED EQUIPMENT (UNUSED RISERS BY ECD'S). PHOTO 23: UNUSED EQUIPMENT (UNUSED RISERS BY ECD'S). PHOTO 24: UNUSED EQUIPMENT (UNUSED RISER NEAR CRUDE OIL TANKS). PHOTO 24: UNUSED EQUIPMENT (UNUSED RISER NEAR HEATED SEPARATOR).		
Corrective Action:	REMOVE OR MARK UNUSED RISERS PER RULE 606.	Date:	10/12/2024
Type	OTHER		
Comment:	PHOTO 26: AREA OF IMPACTED SOIL APPEARS TO BE OILY WASTE FROM DRAINING SEPARATOR ON GROUND. PHOTO 27: AREA OF IMPACTED SOIL APPEARS TO BE OILY WASTE FROM DRAINING SEPARATOR ON GROUND. PHOTO 27: AREA OF IMPACTED SOIL NEAR LEAKING PUMPJACK MOTOR OR GEAR BOX		
Corrective Action:	REMOVE IMPACTED SOIL AND DISPOSE OF PROPERLY, INCREASE Self-inspection, maintenance, and good housekeeping procedures and schedules.	Date:	10/12/2024
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 10: UNUSED EQUIPMENT STORED ON LOCATION (CANVAS TARP). PHOTO 11: UNUSED EQUIPMENT STORED ON LOCATION (POWER CORD). PHOTO 12: UNUSED EQUIPMENT STORED ON LOCATION (EPTY FIBERGLASS BOX AND SOME WATTLE STAKES). PHOTO 13: UNUSED EQUIPMENT STORED ON LOCATION (PALLET OF WATTLES). PHOTO 14: UNUSED EQUIPMENT STORED ON LOCATION (WORK BENCH AND SAW HORSES). PHOTO 15: UNUSED EQUIPMENT STORED ON LOCATION (TRACKOR TIRE, WOOD AND APPEARS TO BE DECK OFF OF A WORKOVER RIG). PHOTO 16: UNUSED EQUIPMENT STORED ON LOCATION (APPEARS TO BE 2 3/8" TUBING).		
Corrective Action:	REMOVE ALL UNUSED EQUIPEMENT FROM LOCATION PER RULE 606. CA DATE 9-18-2024.	Date:	09/18/2024
Type	TRASH		
Comment:	PHOTO 7: TRASH, IT APPEARS TO BE UNED ENGINE OIL IN TWO 5 GAL. BUCKETS NEAR PRIME MOVER. PHOTO 8: TRASH 5 GAL. BUCKETS NEAR WELLHEAD. PHOTO 9: TRASH, SOME KIND OF SCREEN IS DAMAGED.		
Corrective Action:	REMOVE ALL TRASH FROM LOCATION PER RULE 606.	Date:	09/18/2024
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 17: UNUSED EQUIPMENT STORED ON LOCATION (ORANGE 2" POLY PIPE CONNECTED TO PRODUCED WATER TANK IS NOT CONNECTED ON SOUTH END). PHOTO 18: UNUSED EQUIPMENT STORD ON LOCATION (OFFECE AND HEATERS). PHOTO 19: UNUSED EQUIPMENT STORD ON LOCATION (TRUCK, OFFECE AND HEATERS). PHOTO 20: UNUSED EQUIPMENT STORD ON LOCATION (MINING COOLER UNITS AND TANKS). PHOTO 21: UNUSED EQUIPMENT STORD ON LOCATION (MINING COOLER UNITS AND TANKS).		
Corrective Action:	REMOVE ALL UNUSED EQUIPEMENT FROM LOCATION PER RULE 606.	Date:	12/12/2024

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment: BOTH ARE PLUMBED TO SURFACE			
Corrective Action:			Date:
Type: Other	# 2		
Comment: GENERATORS			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment: PRESSURE RELEAF VALVE WAS POPING OFF ALMOST STEADY			
Corrective Action: REPAIR GAS LEAK, SEE FLIRR VIDEO			Date: <u>09/13/2024</u>
Type: Gas Meter Run	# 1		
Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment: OFFICE TRAILER			
Corrective Action:			Date:
Type: Other	# 3		
Comment: BITCOIN MINING TRAILERS			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		38.329088,-105.178627
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	SHARES BERMS WITH PRODUCED WATER TANKS.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 429092 Type: WELL API Number: 043-06216 Status: WO Insp. Status: WO

Workover

Comment: WELL IS WAITING ON COMPLETION

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 430103 Type: WELL API Number: 043-06221 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/20/2023 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 29 Fluid Type: VAPOR

End Surf Csg Pressure: 0

Comment: BRHD TEST PAST DUE
SUBMIT REPORTS.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695110250	FLIR VIDEO OF GAS LEAK	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705715
695110251	INSP PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705716