

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2024

Submitted Date:

09/13/2024

Document Number:

715500657

FIELD INSPECTION FORMLoc ID 312990 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Kirkwood, Tom	(307) 577-5328	tomk@kirkwoodcompanies.com	
Weinert, Dave	(307) 577-5329	davew@kirkwoodcompanies.com	
Hussman, Mark	(307) 277-3333	markh@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222641	WELL	PA	01/13/1992	DA	081-06001	MAULDIN GULCH UNIT 10	PA

General Comment:**ECMC Inspection Report Summary**

On Thursday, 09/12/2024, Inspector Kirby Burchett, conducted a follow up field inspection at Wesco Operating Inc. on the Maudlin Gulch 26 well, Location #312960, in Moffat County, Colorado. UIC Routine inspection was also conducted on the Maudlin Gulch Unit 2 well.

This location is within or close proximity to a Parks & Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. 702502479 on 3/6/24. Corrective Actions have been resolved.

While there during normal operations the following compliance issues were observed:

1. Debris
2. Unused equipment
3. Stained soil
4. Spilled fluid off the edge of location

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: 866-965-6296

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Equipment and supplies left on location		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	09/28/2024
Type	DEBRIS		
Comment:	Random debris from Plug and Abandon operations		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.	Date:	09/27/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		
Lube Oil	WELLHEAD			
Comment:	Several stained areas on location and around wellhead			
Corrective Action:	Remove and properly dispose of any oily waste, stained and impacted soil to an approved facility.			Date: 09/28/2024
PW/CO				
Comment:	Northwest corner of location has evidence of spilled fluid going off location into a natural drainage. Partial cleanup attempted. Due to location perform total cleanup immediately.			
Corrective Action:	Remove and properly dispose of stained and impacted soil to an approved facility.			Date: 09/28/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 6		
Comment:	1 unmarked anchor. Will be removed for reclamation.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	222641	Type:	WELL	API Number:	081-06001	Status:	PA	Insp. Status:	PA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Plugged and Abandoned August 2024"/>									
Corrective Action: <input type="text"/> Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Drains				
		Ditches				

Comment: Well has been plugged and abandoned. Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces until Reclamation is complete.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500659	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6706641