

Interim Reclamation and Stormwater Inspection

Date: 09/10/2024

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 317278

Inspection Document #: 708201604

Washington County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



9/10/24, 10:15 AM
248° W
ECMC

Photo 1. Undesirable vegetation (e.g. kochia and russian thistle) observed at tank battery.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photos 2 & 3. Erosion degradation north of tank battery (left photo) and sediment discharge into adjacent field (right). No apparent perimeter stormwater controls observed.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 4. West side of tank battery; see comments in Photo 2 & 3.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 5. Undesirable vegetation (e.g. kochia and russian thistle) observed at tank battery.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 6. Erosion degradation and sediment discharge observed on the southwest corner of tank battery. No perimeter stormwater controls observed.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 7. Continued from Photo 6, facing northeast.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 8. Erosion degradation and sediment discharge observed west of separator. No perimeter stormwater controls observed.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 9. Continued from Photo 8, photo illustrates rill erosion.



Photo 10. Undesirable vegetation observed north of pit.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 11. Erosion degradation on pit berms.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 12. Close up of void in pit berm, illustrating unconsolidated material.



Photo 13. Western pit berm; evidence of sediment transport and erosion degradation. No apparent perimeter stormwater controls observed.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 14. Southwest corner of pit; see comments in Photo 13.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 15. Erosion degradation on northeast corner of pits.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 16. Visible hydrocarbon at pit.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278




Photo 17. Erosion degradation at well API 121-10211, south side of location.

Inspection Photos
Location Name: Chandler 2-15
Location ID: 317278



Photo 18. Erosion degradation at well API 121-10211, south side of location.