

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2024

Submitted Date:

09/14/2024

Document Number:

715500662

FIELD INSPECTION FORMLoc ID 312766 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------|-----------------------------|---------|
| Weinert, Dave | (307) 577-5329 | davew@kirkwoodcompanies.com | |
| Hussman, Mark | (307) 277-3333 | markh@kirkwoodcompanies.com | |
| Wilson, Justin | (970) 878-3825 | jrwilson@blm.gov | |
| Kirkwood, Tom | (307) 577-5328 | tomk@kirkwoodcompanies.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 222259 | WELL | PR | 11/01/2022 | OW | 081-05228 | TRELEAVEN-GOVERNMENT 3 | PR |

General Comment:**ECMC Inspection Report Summary**

On Thursday, 09/12/2024, Inspector Kirby Burchett, conducted a follow up field inspection at Wesco Operating Inc on the Treleaven-Government 3 well, Location #312766, in Moffat County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District and Black Bear area with High Priority and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715500541 on 8/8/24. FIRR #403902701 submitted by operator stating 4 of 4 Corrective Actions have been addressed. The following Corrective Action is unresolved and original due date remains:

1. Stormwater BMPs not maintained.
Refer to Inspection Photos for observed compliance issues.

While there during normal operations no additional compliance issues were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|------------|-------|--|
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 866-965-6296

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|---------------|-------|--|
| Type | PUMP JACK | | |
| Comment: | Manufacturer | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Corral panels | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------|------------------------------|-------|-----------------|
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Chemical tank on containment | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|-----------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 222259 | Type: | WELL | API Number: | 081-05228 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | July 2024 Production Report | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Stormwater BMPs not maintained

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.
Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 09/08/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 715500663 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6707235 |