

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 9388 From Entrance to location




Photo # 9389 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 9390 Location



Photo # 9391 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114




Photo # 9392 Location



Photo # 9393 Weeds in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 9394 Weeds in secondary containment



Photo # 9395 Weeds in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 3993 From inspection 708904246 conducted on 07/30/2024 Stored supplies on location & in the interim area



Photo # 9396 Stored supplies on location & in the interim area

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 9397 Stored supplies on location & in the interim area



Photo # 9398 Stored supplies on location & in the interim area

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 3994 From inspection 708904246 conducted on 07/30/2024 Stored supplies



Photo # 9399 Stored supplies

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114




Photo # 9400 Wellhead sign has incorrect well # & API #