

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Location Overview: Location is within High  
Priority/Density/NSO/Black Bear Habitat areas. Location is  
approximately 21 yards from a creek & drainage from location  
contributes to the creek.**

**Section/Township/Range: 7 8S92W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8726 Erosion on slope & transport of sediment onto location/insufficient BMP's (east side of location)**



**Photo # 8727 Erosion on slope & transport of sediment onto location/insufficient BMP's (east side of location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8728 Erosion on slope & transport of sediment onto location/insufficient BMP's (east side of location)**



**Photo # 8729 Erosion on slope & transport of sediment onto location/insufficient BMP's (east side of location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8730 Erosion on slope & transport of sediment onto location/insufficient BMP's (east side of location)**



**Photo # 8731 Erosion on slope & transport of sediment onto location/insufficient BMP's (east side of location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8732 Erosion on slope & transport of sediment onto location/insufficient BMP's (east side of location)**



**Photo # 8733 Erosion on slope & transport of sediment onto location/insufficient BMP's (east side of location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8734 Erosion on slope & transport of sediment  
/insufficient BMP's (E/NE area of location)**



**Photo # 8735 Erosion on slope & transport of sediment  
/insufficient BMP's (E/NE area of location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8736 Erosion on slope & transport of sediment /insufficient BMP's (E/NE area of location)**



**Photo # 8737 Erosion on slope & transport of sediment /insufficient BMP's (E/NE area of location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8738 Insufficient BMP's/runoff controls in ditch  
(E/NE area of location near entrance to location)**



**Photo # 8739 Insufficient BMP's/runoff controls in ditch  
(E/NE area of location near entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8740 Insufficient BMP's/runoff controls in ditch, sediment is being carried off location & into a vegetated area & towards a nearby creek/drainage (NE area of location near entrance to location)**



**Photo # 8741 Insufficient BMP's/runoff controls in ditch, sediment is being carried off location & into a vegetated area & towards a nearby creek/drainage (NE area of location near entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8742 Insufficient BMP's/runoff controls in ditch, sediment is being carried off location & into a vegetated area & towards a nearby creek/drainage (NE area of location near entrance to location)**



**Photo # 8743 Insufficient BMP's/runoff controls in ditch, sediment is being carried off location & into a vegetated area & towards a nearby creek/drainage (NE area of location near entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8744 Large amount of sediment & debris built up at culvert inlet/capacity of BMP reduced (on lease road near entrance to location**



**Photo # 8745 Large amount of sediment & debris built up at culvert inlet/capacity of BMP reduced (on lease road near entrance to location**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8746 Erosion & transport of sediment (near entrance to location)**



**Photo # 8747 Erosion & transport of sediment into a vegetated area/BMP's need maintenance (near entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8748 Erosion & transport of sediment off edge of lease road (near culvert on lease road near entrance to location)**



**Photo # 8749 Erosion & transport of sediment off edge of lease road (near culvert on lease road near entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8750 Erosion on slope & transport of sediment off location & into a vegetated area (near Summit Midstream meter house)**



**Photo # 8751 Erosion on slope & transport of sediment off location & into a vegetated area (near Summit Midstream meter house)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8752 Erosion & sediment transport near Rip Rap Run (S/SE area of location)**



**Photo # 8753 Erosion & sediment transport near Rip Rap Run (S/SE area of location)**