

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad

Location #: 334291



Photo # 8715 From Entrance to location




Photo # 8716 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad

Location #: 334291



Photo # 8717 Location



Photo # 8718 Location




## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad

Location #: 334291



**Photo # 8719 Location**



**Photo # 8720 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad**  
**Location #: 334291**



**Photo # 8721 Tank label damaged/does not comply with CECMC labeling rules**



**Photo # 8722 Tank label damaged/does not comply with CECMC labeling rules**





## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad

Location #: 334291



Photo # 8723 Location



Photo # 8724 Small amount of damage/buckling on secondary containment

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 7-14 (N7SE) Pad

Location #: 334291



**Photo # 8725 Small amount of damage/buckling on secondary containment**