

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 36-15A (C36W) Pad

Location #: 334336



Photo # 8423 From Entrance to location



Photo # 8424 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 36-15A (C36W) Pad

Location #: 334336



Photo # 8425 Location



Photo # 8426 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 36-15A (C36W) Pad

Location #: 334336



Photo # 8427 Location



Photo # 8428 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 36-15A (C36W) Pad

Location #: 334336



Photo # 8429 Location



Photo # 8430 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 36-15A (C36W) Pad

Location #: 334336



Photo # 8431 Location



Photo # 8432 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 36-15A (C36W) Pad

Location #: 334336



Photo # 8433 Location



Photo # 8434 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 36-15A (C36W) Pad

Location #: 334336



Photo # 8435 Location



Photo # 8436 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 36-15A (C36W) Pad

Location #: 334336



Photo # 8437 Barbed wire fence needs maintenance/wildlife hazard



Photo # 8438 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 36-15A (C36W) Pad

Location #: 334336



Sep 6, 2024 at 10:34:39 AM

Photo # 8439 Barbed wire fence needs maintenance/wildlife hazard



Sep 6, 2024 at 10:35:21 AM

Photo # 8440 Barbed wire fence needs maintenance/wildlife hazard