

Inspection Photos

API: 071-09757

Operator: OGRIS OPERATING LLC

Inspection Date: 9/16/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the wellsite.



Inspection Photos



Photo 2. The well is protected with a steel grate.



Inspection Photos



Photo 2. Facing northeast toward the topsoil pile.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09757 | Date: 9/16/2024

Inspection Photos



Photo 4. Facing west at the north side of the location. The topsoil piles could be utilized along this area for recontouring.



Inspection Photos



Photo 2. Facing west toward the topsoil pile. There are undesirable weeds on and around the topsoil pile. The topsoil pile needs to be replaced for reclamation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09757 | Date: 9/16/2024