

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2024

Submitted Date:

09/13/2024

Document Number:

707801096

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 316758 _____ Ramsey, Scott _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: _____ 6720 _____
 Name of Operator: ROBERT L BAYLESS PRODUCER LLC _____
 Address: 621 17TH ST STE 2300 _____
 City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80293 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 _____ Number of Comments
 5 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	
Thomas, John	505-326-2659	jthomas@rlbayless.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232649	WELL	SI	01/01/2024	GW	107-06063	DRY CREEK UNIT 3-22	PR

General Comment:[ECMC Inspection Report Summary](#)

On Monday 8/19/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Bayless Dry Creek 3-22, at Location # 316758 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Battery signage lacking information
2. Tank labeling lacking information
3. No evidence of bird protection on heat treater
4. Some stained material
5. 1 anchor not marked properly

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank labeling lacking information		
Corrective Action:	Provide proper labeling	Date:	10/18/2024
Type	BATTERY		
Comment:	Battery signage lacking information		
Corrective Action:	Provide proper signage	Date:	10/18/2024
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text" value="(505)327-0880/911"/>		Date:
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Some stained material		
Corrective Action:	Remove stained material, dispose of properly and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.	Date:	10/18/2024
Type	OTHER		
Comment:	No evidence of bird protection on heat treater		
Corrective Action:	Provide proper bird protection or proof of protection	Date:	10/18/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 1	
Comment:	1 anchor not marked properly	
Corrective Action:	Mark or remove anchor	Date: 10/18/2024
Type: Ancillary equipment	# 1	
Comment:	Propane tank	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	Possibly 2	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 232649 Type: WELL API Number: 107-06063 Status: SI Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801099	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709342