

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2024

Submitted Date:

09/17/2024

Document Number:

709100404

**FIELD INSPECTION FORM**

Loc ID 470775 Inspector Name: Heibel, Krystal On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 76830  
Name of Operator: SCHMID PROPERTIES INC  
Address: PO BOX 389  
City: HICO State: TX Zip: 76457

**Findings:**

- 7 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Kym Schure		kym.schure@state.co.us	
Schmid, William	337-261-1500	tenniswilliam123@cs.com	
Kyle Waggoner		kyle.waggoner@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
470775	Location	AC			-	Clark Treater	EI

**General Comment:**

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

This environmental field inspection is in response to the Compliance Unit field inspection, Doc# 711901265, submitted on Sept 11, 2024.

<b>Location</b>			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type			
Comment:	Sign or label not posted on blue barrel		
Corrective Action:	Install sign to comply with Rule 605.h.(3).		Date: <u>12/15/2024</u>
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds observed around the facility and pits. Tumbleweeds observed in metal shed.		
Corrective Action:	Comply with Rule 606		Date: <u>10/01/2024</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (metal pipe and barrel) observed at location		
Corrective Action:	Comply with Rule 606		Date: <u>10/01/2024</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Crude Oil			
Comment:	Crude oil observed in small pit beside partially-buried vessel. Environmental Protection Specialist called the emergency contact number while on location. Owner Bill Schmid sent Pumper Tim to get the vac-truck out same-day to remediate the release.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Operator shall submit a Spill/Release Report (Form 19 Initial) to the ECMC within 72 hours with photos of the cleanup. Operator shall collect soil sample(s) for Full Table 915-1 analytes to ensure remediation is complete.		Date: <u>09/13/2024</u>
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type:	#		corrective date
Comment:	Valves within metal shed observed to be not bull plugged or fastened. See photo documentation.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>10/17/2024</u>
<b>Tanks and Berms:</b>			
Contents	#	Capacity	Type
Comment:			
Corrective Action:			Date:
<b>Paint</b>			

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <span style="color: blue;">Holes observed in berms.</span>				
Corrective Action: <span style="color: red;">Repair or install berms or other secondary containment devices per Rule 603.o.</span>				Date: <u>11/17/2024</u>

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 470775 Type: Location API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100405	Pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709988">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709988</a>