

Inspection Photos

ID: 453010

Operator: OGRIS OPERATING LLC

Inspection Date: 9/16/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the main road to the compressor facility. There is erosion occurring at the red arrow which is directing sediment onto the main road. Sediment needs to be removed from the paved road and sediment controlled.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 9/16/2024

Inspection Photos



Photo 2. Facing northeast along the main paved road. The sediment and gravel along this area should be cleaned out to prevent sediment movement onto the paved road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 9/16/2024