

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2024

Submitted Date:

09/17/2024

Document Number:

717700502

FIELD INSPECTION FORMLoc ID 317912 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10528

Name of Operator: ARCH OIL & GAS LLC

Address: 16400 DALLAS PARKWAY SUITE 305

City: DALLAS State: TX Zip: 75248

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HEASLIP, TRACY	(239) 404-0929	theaslip@archog.com	All Inspections
,		dnr_cogccengineering@state.co.us	
Collins, Kilian		kilian.collins@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240164	WELL	SI	09/01/2020	OW	123-07952	KAUFMAN 4	SI

General Comment:

This is an audit on the well.

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Overgrown vegetation needs to be removed for good housekeeping.		
Corrective Action:	Comply with Rule 606	Date:	09/27/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused Pumping unit needs to be removed good housekeeping.		
Corrective Action:	Comply with Rule 606	Date:	12/31/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Safety Fence around the open hole needs to be repaired.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	09/27/2024

Equipment:

Type: Prime Mover	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
------	--	--	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 240164 Type: WELL API Number: 123-07952 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well appears to be plugged, Cut & Capped
Form 42(PA) #403747542
Form 6(N) #403742109 no Form 6(S) on file
Form 27(I) #403763340

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary On Monday September 16, 2024, at approximately 8:40 AM, Inspector Adam Burns conducted an on-site inspection at the following location: Well: Kaufman 4 Operator: Arch Oil & Gas LLC API: 05-123-07952 County: Weld During the inspection, a producing well was observed. The following possible compliance issues were identified: Fencing: Safety Fence around the open hole needs to be repaired. Comply with the fencing requirements per the 1002a rules Housekeeping: Overgrown vegetation needs to be removed for good housekeeping. Comply with Rule 606 Housekeeping: Unused Pumping unit needs to be removed good housekeeping. Comply with Rule 606 A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.	burnsa	09/17/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717700503	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6710437