

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2024

Submitted Date:

09/17/2024

Document Number:

714300132

FIELD INSPECTION FORMLoc ID 332269 Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------|-------------------|
| Rollins, Grace | | grace.rollins@state.co.us | |
| , | | ECMCInspections@Oxy.com | All Inspections |
| Mickelson, Erik | | Erik_Mickelson@oxy.com | Oxy Environmental |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|-------------------------|-------------|
| 332269 | LOCATION | AC | | | - | VARGAS-62N67W 13NESW | EI |

General Comment:

This is an environmental inspection to determine progress on Remediation Project No 34982. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

| Type | Area | Volume | | |
|--|----------|--------|--|--|
| In Containment: No | Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Fencing/:

| Type | | | |
|--------------------|--|-------|------------|
| Comment: | Orange construction fencing down around portions of the open excavation. | | |
| Corrective Action: | Secure access to excavation in compliance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v | Date: | 09/24/2024 |

Venting:

| Yes/No | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| Type | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|----------|-------------|---|---------|----|---------------|----|
| Facility ID: | 332269 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | EI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation project 34982 crated for the decommissioning of the Kerr14-13A/EastM/Var tank battery. Multiple excavations were open on the location. No environmental impacts were visible in-situ and no groundwater was observed in the open excavation. Quarterly reporting was required under remediation project No 34982; the last Form 27 for this project was submitted 4/5/2024 (doc no 403742907).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation #34982.

Date: 10/01/2024

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Lat _____

Long _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

| Type | Management | Condition | GPS (Lat) | (Long) |
|------|------------|-----------|-----------|--------|
|------|------------|-----------|-----------|--------|

| | | | | |
|--|--|--|--|--|
| | | | | |
|--|--|--|--|--|

| | |
|---------|---|
| Comment | Multiple soil stockpiles on location, many without BMPs |
|---------|---|

| | |
|-------------------|--|
| Corrective Action | Install or repair required BMPs per Rule 1002.f.(2)C |
|-------------------|--|

Date: 10/01/2024

Spill/Remediation:

Comment: _____

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 714300133 | Insp Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711304 |