

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2024

Submitted Date:

09/18/2024

Document Number:

715500666

FIELD INSPECTION FORMLoc ID 315117 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Saint, John		jsaint@scoutep.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Christian, Cody		Cody.Christian@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230282	WELL	PR	04/01/2024	OW	103-07942	FEDERAL 12-6	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 09/17/2024, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Management LLC on the Federal 12-6 well, Location #315117, in Rio Blanco County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District with High Priority, NSO and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issue observed during Insp. #702501927 on 10/2/23 and Insp. #702501589 on 6/29/23. The Corrective Action has been resolved by ECMC Engineering on 10/24/23 with the approval of an Aternate MIT.

While there during normal operations the following compliance issues were observed:

1. Debris
2. Staining
3. Unused equipment
4. Unlabeled chemical tank

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical tank missing required labeling		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	09/28/2024
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Supplies and equipment storage on location		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	10/03/2024
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.	Date:	09/25/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	
Other			
Comment:	Large stain North of wellhead		
Corrective Action:	Remove and properly dispose of any oily waste, stained and contaminated soil to an approved facility.		Date: 10/03/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Manufacturer		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment:	Double metal rail			
Corrective Action:			Date:	

Equipment:

Type: Ancillary equipment	# 2			corrective date
Comment:	Chemical tanks on containment			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	230282	Type:	WELL	API Number:	103-07942	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	June 2024 Production Report. Operators will report all existing oil and gas Wells that are not Plugged and Abandoned on the Form 7, Operator's Monthly Report of Operations within 45 days after the end of each month.								
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Tracking Pad						
				Material Handling And Spill Prevention		
		Tracking Pad				
Berms						
		Culverts				
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500668	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6713224