

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



Photo # 662 From entrance to location



Photo # 663 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



Photo # 664 Location



Photo # 665 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



**Photo # 5373 From inspection 708903672 conducted on 04/29/2024 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules**



**Photo # 666 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules**

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



**Photo # 5374 From inspection 708903672 conducted on 04/29/2024 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules**



**Photo # 667 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules**

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



**Photo # 5375 From inspection 708903672 conducted on 04/29/2024 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 668 PRV vent line does not comply with CECMC pressure safety device rules**