

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2024

Submitted Date:

09/18/2024

Document Number:

708302752**FIELD INSPECTION FORM**

Loc ID 334813	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	------------------------------------	---	-------------------

Operator Information:

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210929	WELL	PR	06/15/1998	GW	045-06687	SAVAGE GV 80-4	PR
294526	WELL	PR	02/14/2013	GW	045-15509	SAVAGE PA 524-4	PR
294527	WELL	PR	02/28/2010	GW	045-15510	SAVAGE PA 523-4	PR
294528	WELL	PR	02/28/2010	GW	045-15511	SAVAGE PA 513-4	PR
294529	WELL	PR	01/02/2015	GW	045-15512	SAVAGE PA 414-4	PR
299742	WELL	PR	02/14/2013	GW	045-17746	SAVAGE PA 324-4	PR
299743	WELL	PR	04/01/2015	GW	045-17747	SAVAGE PA 14-4	PR
299744	WELL	PR	02/28/2010	GW	045-17748	SAVAGE PA 24-4	PR
419921	WELL	PR	04/30/2013	GW	045-20058	Savage PA 44-5	PR
419922	WELL	PR	03/31/2013	GW	045-20059	Savage PA 443-5	PR
419925	WELL	PR	04/30/2013	GW	045-20061	Savage PA 444-5	PR
419936	WELL	PR	05/14/2013	GW	045-20064	Savage PA 13-4	PR
419941	WELL	PR	05/14/2013	GW	045-20066	Savage PA 423-4	PR
419972	WELL	PR	02/03/2013	GW	045-20075	Savage PA 514-4	PR
419975	WELL	PR	04/15/2013	GW	045-20077	Savage PA 413-4	PR
419979	WELL	PR	05/14/2013	GW	045-20080	Savage PA 323-4	PR
419989	WELL	PR	01/31/2013	GW	045-20083	Savage PA 424-4	PR
419994	WELL	PR	05/14/2013	GW	045-20085	Savage PA 313-4	PR
419995	WELL	PR	04/30/2013	GW	045-20086	Savage PA 344-5	PR
420005	WELL	PR	03/15/2013	GW	045-20090	Savage PA 314-4	PR
420012	WELL	PR	04/30/2013	GW	045-20092	Savage PA 43-5	PR

420095	WELL	PR	04/15/2013	GW	045-20099	Savage PA 343-5	PR
420096	WELL	PR	03/15/2013	GW	045-20100	Savage PA 544-5	PR

General Comment:

[CECMC Inspection Report Summary](#)

On 9/17/2024 at approximately 10:55, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, Savage/GV 80-4 at Location ID #334813 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Damaged fencing at tank battery

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign unreadable due to fence damage.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Damaged hog panel fencing at tank battery.		
Corrective Action:	Repair fencing to comply with CECMC General Safety and Housekeeping rules.	Date:	10/02/2024

Equipment:				corrective date	
Type: Plunger Lift	# 3				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Air compressor				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 3				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 20				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 20				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 13				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 20				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 20				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:	Chemical tanks				
Corrective Action:				Date:	
Type: Gas Meter Run	# 3				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 3				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	CataFlow				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities				
Facility ID:	210929	Type:	WELL	API Number: 045-06687 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	294526	Type:	WELL	API Number: 045-15509 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	294527	Type:	WELL	API Number: 045-15510 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	294528	Type:	WELL	API Number: 045-15511 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	294529	Type:	WELL	API Number: 045-15512 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299742	Type:	WELL	API Number: 045-17746 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299743	Type:	WELL	API Number: 045-17747 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299744	Type:	WELL	API Number: 045-17748 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	419921	Type:	WELL	API Number: 045-20058 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	419922	Type:	WELL	API Number: 045-20059 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	419925	Type:	WELL	API Number: 045-20061 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	419936	Type:	WELL	API Number: 045-20064 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	419941	Type:	WELL	API Number: 045-20066 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	419972	Type:	WELL	API Number: 045-20075 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	419975	Type:	WELL	API Number: 045-20077 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	419979	Type:	WELL
API Number:	045-20080	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	419989	Type:	WELL
API Number:	045-20083	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	419994	Type:	WELL
API Number:	045-20085	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	419995	Type:	WELL
API Number:	045-20086	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	420005	Type:	WELL
API Number:	045-20090	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	420012	Type:	WELL
API Number:	045-20092	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	420095	Type:	WELL
API Number:	045-20099	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Facility ID:	420096	Type:	WELL	API Number:	045-20100	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:			
Corrective Action:			Date: <div></div>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
Gravel						
		Compaction				
		Ditches				
Berms						
Compaction						
		Gravel				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302753	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6713294