

Operator: CPR

Location Name: CHAPIN 61N65W / 4 SESE

Loc ID: 331608

Inspection: 708201515







CA: This location does not comply with Rule 1004. Reclamation rules require reclamation activities to be conducted within twelve months of plugging on non-cropland. Well was plugged 04/09/2018. It does not appear any reclamation work has been performed; gravel remains throughout the location, which has not been contoured or graded to reflect pre-disturbance levels. It appears that the original footprint of the former well location was expanded for plugging and abandonment operations but was never reduced in size and reclaimed. Former well is within an active location. Refer to attached inspection photos. Perform reclamation in accordance with Rule 1004.

CA Resolution: Operator has reported that the location has also been mowed, line trimmed. It has also been noted that the road base removal and seeding has been scheduled.

CA: This location does not comply with Rule 1002.f. During this inspection, it was observed that the western portions of the pad are experiencing erosion degradation (e.g. gullyng) with evidence of sediment deposition outside of the location. The pad seems to have been extended beyond the original well footprint and has not been reclaimed since the well was plugged and abandoned. Once final reclamation activities are completed for the former well location, the area will need to have adequate stormwater BMPs to manage stormwater for the reclaimed portions. Refer to attached inspection photos. Comply with Rule 1002.f.

CA Resolution: Operator has reported that identified areas of erosion have been appropriately stabilized and riprap refreshed to comply with Rule 1002.f.