

**Operator:** CPR

**Location Name:** CHAPIN 61N65W / 4 SESE

**Loc ID:** 331608

**Inspection:** 708201512







**CA:** Trash, debris and unused equipment was observed throughout the location. Refer to attached inspection photos for examples. Comply with Rule 606 and remove any trash/debris and unused equipment from location.

**CA Resolution:** Operation has addressed identified trash/debris and location now complies with the 600 series.

**CA:** This location does not comply with Rule 1003. During this inspection, it was observed that the interim areas do not appear to be progressing towards Rule 1003 regulations and standards with undesirable vegetation (Russian thistle) and CO ist B Noxious Weed (Russian olive) observed to be growing throughout. Additionally, production areas do not appear to be properly stabilized with erosion degradation observed (refer to Stormwater Section for additional information). Refer to attached inspection photos. Perform reclamation in accordance with Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. se a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil and continue to monitor and manage this site until the location meets Rule 1003 standards.

**CA Resolution:** Operator has reported that the location has also been mowed, line trimmed. It has also been noted that the road base removal and seeding has been scheduled.

**CA:** This location does not comply with Rule 1002.f. During this inspection, it was observed that the western portions of the pad are experiencing erosion degradation (e.g. gullyng) with evidence of sediment deposition outside of the location. The pad seems to have been extended beyond the original well footprint and has not been reclaimed since the well was plugged and abandoned. Once final reclamation activities are completed for the former well location, the area will need to have adequate stormwater BMPs to manage stormwater for the reclaimed portions. Refer to attached inspection photos. Comply with Rule 1002.f.

**CA Resolution:** Operator has reported that identified areas of erosion have been appropriately stabilized and riprap refreshed to comply with Rule 1002.f.