

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2024

Submitted Date:

09/19/2024

Document Number:

713400329

FIELD INSPECTION FORM

Loc ID 334539	Inspector Name: Popejoy, Dusty	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 18 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE			
Operator Information: ECMC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1700 LINCOLN ST STE 3950 City: DENVER State: CO Zip: 80203							
Contact Information:							
Contact Name		Phone	Email	Comment			
Kellerby, Shaun			shaun.kellerby@state.co.us				
, LARAMIE			cogccnotifications@laramie-energy.com				
Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287062	WELL	PR	10/24/2008	GW	077-09151	UTE WATER 22-10	PR
287063	WELL	PR	11/01/2010	GW	077-09150	UTE WATER 22-11	PR
287064	WELL	PR	12/20/2007	GW	077-09149	UTE WATER 22-12	PR
287065	WELL	PR	03/01/2017	GW	077-09148	UTE WATER 22-13	PR
287066	WELL	PR	04/01/2024	GW	077-09147	UTE WATER 22-14	PR
287067	WELL	PR	03/01/2017	GW	077-09146	UTE WATER 22-15	PR
287068	WELL	PR	03/01/2017	GW	077-09145	UTE WATER 27-2	PR
287069	WELL	PR	03/01/2017	GW	077-09144	UTE WATER 27-3	PR
General Comment: CECMC Inspection Report Summary On 9/17/2024 at approximately 14:57, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Ute Water/22-14 Pad at Location ID #334539 in Mesa County, Colorado. This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area. During the inspection, the following compliance issues were observed: Housekeeping: 1- Loose barbed wire on northeast corner of location/wildlife hazard with a CA date of 9/26/2024 Equipment: 2- Methanol tank hatch is open to wildlife with a CA date 9/26/2024 A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.							

Location

Lease Road:			
Type	Access		
comment:	Access.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	1 condensate tank label is peeling.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/1-800-891-6191

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Loose barbed wire on northeast corner of location/wildlife hazard, refer to photos.		
Corrective Action:	Comply with CECMC wildlife rules.	Date:	09/26/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Methanol tank hatch is open to wildlife/ available for entry by wildlife, refer to photos.		
Corrective Action:	Comply with CECMC wildlife rules.	Date:	09/26/2024
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 8	
Comment:	All Bradenhead valves are accessible.	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 8	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 8	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:	500 gal				
Corrective Action:					Date:

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	500 gal
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLs	STEEL AST		,
Comment:	Telemetry on 3 tanks.				
Corrective Action:					Date:

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities				
Facility ID:	287062	Type:	WELL	API Number: 077-09151 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287063	Type:	WELL	API Number: 077-09150 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287064	Type:	WELL	API Number: 077-09149 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287065	Type:	WELL	API Number: 077-09148 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287066	Type:	WELL	API Number: 077-09147 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287067	Type:	WELL	API Number: 077-09146 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287068	Type:	WELL	API Number: 077-09145 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287069	Type:	WELL	API Number: 077-09144 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing well.		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gravel						
Compaction						
		Ditches				
Ditches						
		Compaction				
		Berms				
Berms						
Seeding						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400331	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6714663