

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2024

Submitted Date:

09/19/2024

Document Number:

708904623

FIELD INSPECTION FORM

Loc ID 334521 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

32 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
LARAMIE ENERGY		cogccnotifications@laramie-energy.com	
Popejoy, Dusty		dusty.popejoy@state.co.us	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278014	WELL	PR	02/01/2014	GW	077-08896	HELLS GULCH FEDERAL 24-13	PR
278016	WELL	PR	03/01/2015	GW	077-08894	HELLS GULCH FEDERAL 26-2	PR
278017	WELL	PR	02/01/2014	GW	077-08893	HELLS GULCH FEDERAL 26-11	PR
292341	WELL	PR	04/23/2009	GW	077-09398	HELLS GULCH FED. 23-15A	PR
292342	WELL	PR	04/23/2009	GW	077-09397	HELLS GULCH FED. 23-15B	PR
292343	WELL	PR	10/16/2009	GW	077-09396	HELLS GULCH FED. 23-15C	PR
292344	WELL	PR	10/18/2018	GW	077-09399	HELLS GULCH FED. 25-5	PR
292345	WELL	PR	01/01/2011	GW	077-09395	HELLS GULCH FED. 26-2A	PR
292346	WELL	PR	01/01/2011	GW	077-09394	HELLS GULCH FED. 26-2B	PR
292348	WELL	PR	10/01/2008	GW	077-09392	HELLS GULCH FED. 23-15	PR

General Comment:

CECMC Inspection Report Summary

On 09/19/2024 at approximately 16:46 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at LARAMIE ENERGY LLC Hells Gulch Federal 26-7 Pad.
Location # 334521 in Mesa County Colorado.
Location is within High Priority/Density/NSO/Black Bear Habitat areas.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Failure to maintain chemical BMP with a CA date of 09/20/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	24-13 wellhead sign weathered & cracking but still legible at this time		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank label on methanol tank damaged/some required info becoming illegible - please refer to photo log		
Corrective Action:			Date:
Type	OTHER		
Comment:	Chemical tanks on separators labeled		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	1-800-891-6191/911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Small amount of weeds in secondary containment		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 10		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Thermoelectric generator		
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:	No form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		

Comment:		Centralized containment				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	4	400 BBLs	STEEL AST		,		
Comment:		2 of the 4 tanks equipped with telemetry				Date:	
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient					
Comment:		Centralized containment				Date:	
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:							
Flaring:							
Type							
Comment:							
Corrective Action:							

Inspected Facilities									
Facility ID:	278014	Type:	WELL	API Number:	077-08896	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	278016	Type:	WELL	API Number:	077-08894	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	278017	Type:	WELL	API Number:	077-08893	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	292341	Type:	WELL	API Number:	077-09398	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	292342	Type:	WELL	API Number:	077-09397	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	292343	Type:	WELL	API Number:	077-09396	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	292344	Type:	WELL	API Number:	077-09399	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	292345	Type:	WELL	API Number:	077-09395	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292346 Type: WELL API Number: 077-09394 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292348 Type: WELL API Number: 077-09392 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small amount of light compaction
Berms						
		Compaction				
Sediment Traps						
Gravel						Sparse to none in some areas
		Culverts				
		Gravel				Sparse to none in sections
Ditches						
Rip Rap						
				Material Handling And Spill Prevention	Fail	Failure to maintain chemical BMP
		Ditches				

Comment: 1. Failure to maintain chemical BMP/chemical tank containment full of fluid/BMP insufficient to contain possible spill (Fluid on the top of chemical tank containment is also a wildlife hazard)

At approximately 17:33 hours I called & spoke with Kenny Sackett with Laramie Energy & informed him about the chemical tank containment being full of fluid. I went on to inform him that I was issuing a 24 hour corrective action on the observed compliance issue. He said he'd have someone out in the morning to pull the fluid from the containment. I also informed him that the standing fluid on top of the containment was a wildlife hazard.

Corrective Action: **Comply with CECMC Stormwater rules**

Date: 09/20/2024

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Stormwater for corrective action & also refer to Signs/Marker & Housekeeping for comments.	smelserw	09/19/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904624	Inspection 708904623 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6714829
708904625	Inspection 708904623 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6714830