

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2024

Submitted Date:

09/13/2024

Document Number:

715500657

**FIELD INSPECTION FORM**

Loc ID 312990 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 95520  
Name of Operator: WESCO OPERATING INC  
Address: 120 S DURBIN STREET  
City: CASPER State: WY Zip: 82602

**Findings:**

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Kirkwood, Tom	(307) 577-5328	tomk@kirkwoodcompanies.com	
Weinert, Dave	(307) 577-5329	davew@kirkwoodcompanies.com	
Hussman, Mark	(307) 277-3333	markh@kirkwoodcompanies.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222641	WELL	PA	01/13/1992	DA	081-06001	MAULDIN GULCH UNIT 10	PA

**General Comment:**

[ECMC Inspection Report Summary](#)

On Thursday, 09/12/2024, Inspector Kirby Burchett, conducted a follow up field inspection at Wesco Operating Inc. on the Maudlin Gulch 26 well, Location #312960, in Moffat County, Colorado. UIC Routine inspection was also conducted on the Maudlin Gulch Unit 2 well.

This location is within or close proximity to a Parks & Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. 702502479 on 3/6/24. Corrective Actions have been resolved.

While there during normal operations the following compliance issues were observed:

1. Debris
2. Unused equipment
3. Stained soil
4. Spilled fluid off the edge of location

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**

Overall Good:

Emergency Contact Number:

Comment: 866-965-6296

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Equipment and supplies left on location		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.		Date: 09/28/2024
Type	DEBRIS		
Comment:	Random debris from Plug and Abandon operations		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.		Date: 09/27/2024

Overall Good:

**Spills:**

Type	Area	Volume	
PW/CO			
Comment:	Northwest corner of location has evidence of spilled fluid going off location into a natural drainage. Partial cleanup attempted. Due to location perform total cleanup immediately.		
Corrective Action:	Remove and properly dispose of stained and impacted soil to an approved facility.		Date: 09/28/2024
Lube Oil	WELLHEAD		
Comment:	Several stained areas on location and around wellhead		
Corrective Action:	Remove and properly dispose of any oily waste, stained and impacted soil to an approved facility.		Date: 09/28/2024

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Deadman # & Marked	# 6		corrective date
Comment:	1 unmarked anchor. Will be removed for reclamation.		
Corrective Action:			Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 222641 Type: WELL API Number: 081-06001 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Drains				
		Ditches				

Comment: Well has been plugged and abandoned. Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces until Reclamation is complete.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403920887	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6706660">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6706660</a>
715500659	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6706641">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6706641</a>