

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2024

Submitted Date:

09/18/2024

Document Number:

711901281

FIELD INSPECTION FORM

Loc ID: 317087 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95800
Name of Operator: WESTGATE OIL CO
Address: 403 N MYRTLE
City: EUREKA State: KS Zip: 67045

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hough, Kevin		houghkevin@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236054	WELL	PR	07/01/2018	OW	121-08544	DANIELS 1	PR

General Comment:

ROUTINE FIR 2024

Location

Lease Road:			
Type	Access		
comment:	MAINTAIN LEASE ROAD		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:	REMOVE TUBING LAYING ON GROUND: SEE ATTACHED PHOTO	Date:	09/30/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: NONE

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment:	NO CHANGE		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 236054 Type: WELL API Number: 121-08544 Status: PR Insp. Status: PR

Producing Well

Comment: OW

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>REMOVE TUBING LAYING ON GROUND</u>	schureky	09/18/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
711901282	REMOVE TUBING	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715175