

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Other

2

Comment: [generators for bitcoin minning](#)

Corrective Action:

Date:

Type: Other

1

Comment: [heat exchanger](#)

Corrective Action:

Date:

Type: Vertical Heater Treater

1

Comment:

Corrective Action:

Date:

Type: Emission Control Device

2

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: [PHOTO 5: Meter not calibrated annually.](#)

Corrective Action: [Calibrate gas metering equipment annually to comply with rule 430.d.\(1\). Ca date 10/20/2024.](#)

Date: 10/20/2024

Type: Other

3

Comment: [bitcoin minning trailers](#)

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:	PRESSURE RELIEF VALVE IS POPPING OFF ALMOST CONTANT AND IS LEAKING GAS ON NORTH END OF SEPARATOR INSIDE AN ENCLOSED CONPARTMENT OF SEPARATOR. NOTE: MY PERSONAL PROTECTION GAS DETECTOR WAS SOUNDING OFF WHEN I CAME TO CLOSE TO THE SEPARATOR.	
Corrective Action:	ENSURE PRESSURE RELIEF VALVE IS APPERATING PROPERLY, DO NOT US PRESSURE RELIEF VALVE TO REGULATE EXCESSIVE BACK PRESSURE, COMPLY WITH RULE 608.e.	Date: 09/21/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		38.328900,-105.178860

Comment:	
Corrective Action:	Date:

Paint

Condition Adequate	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 430103 Type: WELL API Number: 043-06221 Status: SI Insp. Status: SI

Producing Well

Comment: pr

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/20/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 29 Fluid Type: VAPOR

End Surf Csg Pressure: 0

Comment: CORRECTIVE ACTION TO SUBMIT BRHD TEST REPORTS IS ON PREVIOUS INSPECTION AND IS STILL VALID

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716300021	SOUND VIDEO	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715857
716300022	FLIR VIDEO	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715858
716300023	INSP PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715859