

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2024

Submitted Date:

09/20/2024

Document Number:

708904632

FIELD INSPECTION FORM

Loc ID 335478 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Katz, Aaron		aaron.katz@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296693	WELL	PR	05/20/2009	GW	045-16101	SAVAGE RWF 411-26	PR
297597	WELL	PR	05/20/2009	GW	045-16886	SAVAGE RMV 149-26	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 09/19/2024 at approximately 12:00 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RWF22-26 Pad. Location # 335478 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area & Bald Eagle Roost Site. Location is approximately 450 yards from Porcupine Creek. Location is approximately 475 yards from Beaver Creek. While there, I observed workover rig performing casing repair on the SAVAGE RWF 411-26 well.

During this inspection the following compliance issues were observed:

1. Inspected Facilities - Failure to comply with COA on SAVAGE RWF411-26 well with a CA date of 9/18/2024
2. Inspected Facilities - Failure to comply with COA on SAVAGE RMV 149-26 with a CA date of 9/19/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
This is a summary of inspection report.

This inspection is limited in scope focusing primarily on the SAVAGE RWF 411-26 & SAVAGE RMV 149-26 wells.

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Rig sign at intersection of county road & start of lease road		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Rig pump		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Workover rig		
Corrective Action:			Date:
Type: Other	# 6		
Comment:	Fire extinguishers		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Rig tank		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Accumulator		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 296693 Type: WELL API Number: 045-16101 Status: PR Insp. Status: PR

Workover

Comment: Please refer to FORM 4 SUNDRY document # 403782337
 Operator has failed to comply with condition of approval, well was to be repaired or plugged no later than 9/18/2024.

Corrective Action: **Contact CECMC Engineering Group & discuss observed compliance issue.** Date: 09/27/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297597 Type: WELL API Number: 045-16886 Status: PR Insp. Status: PR

Cement

Cement Contractor

Contractor Name: _____ Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: Please refer to FORM 4 SUNDRY document # 403782358
 Operator has failed to comply with condition of approval, well was to be repaired or plugged no later than 9/19/2024. At time of inspection well had not been repaired or plugged.
 Spoke with TEP consultant & was informed that the rig would be moving to this well to perform plugging operations early next week.

Corrective Action: **Contact CECMC Engineering Group & discuss observed compliance issue.** Date: 09/27/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Inspected Facilities for corrective actions.	smelserw	09/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904633	Inspection 708904632 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715942