

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2024

Submitted Date:

09/15/2024

Document Number:

708904584

**FIELD INSPECTION FORM**

Loc ID: 324114    Inspector Name: Smelser, Wayne    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 16 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER    State: CO    Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258576	WELL	PR	01/13/2004	GW	045-07644	CEDAR SPRINGS RANCH 2-14 (N2W)	PR

**General Comment:**

CECMC Inspection Report Summary  
 On 09/10/2024 at approximately 11:24 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad. Location # 324114 in Garfield County Colorado.  
 Please refer to inspection 708904246 conducted on 07/30/2024, previous corrective action has not been completed & CA date remains 08/29/2024  
 Location is within High Priority/Density/Black Bear Habitat areas.  
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Stored supplies & equipment on location & in the interim area with a CA date of 08/29/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
 This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign has incorrect well # & API # - please refer to photo log Second wellhead sign located at separator		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Stored supplies on location & in the interim area		
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.		Date: <u>08/29/2024</u>
Type	WEEDS		
Comment:	Small amount of weeds in secondary containment - please refer to photo log		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment:	No		
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		

Comment: <a href="#">Well on plunger lift</a>		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment: <a href="#">Summit Midstream</a>		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		Date:
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: <a href="#">Pressure transducer located on bradenhead, bradenhead valve is accessible.</a>		Date:
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment: <a href="#">Tank equipped with telemetry</a>					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment: <a href="#">Unlined containment</a>				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO	
Comment:		Date:
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 258576 Type: WELL API Number: 045-07644 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Compaction				
		Gravel				Sparse
Gravel						Sparse to none in areas
Compaction						Small amount of light compaction
		Ditches				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Housekeeping for corrective action &amp; also refer to Signs/Marker for comments.</a>	smelserw	09/15/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403921352	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6707789">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6707789</a>
708904585	Inspection 708904584 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6707784">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6707784</a>
708904586	Inspection 708904584 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6707785">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6707785</a>