

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2024

Submitted Date:

09/22/2024

Document Number:

708904640

FIELD INSPECTION FORMLoc ID 311653 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

25 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Aaron		aaron.trujillo@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285306	WELL	PR	06/15/2007	GW	045-12424	OVERACKER 29-03D	PR
285308	WELL	PR	06/10/2009	GW	045-12422	OVERACKER 29-04B	PR
288105	WELL	PR	06/10/2009	GW	045-13157	OVERACKER FED. 20-14D	PR
288106	WELL	PR	06/10/2009	GW	045-13156	OVERACKER FED. 29-05B	PR

General Comment:**CECMC Inspection Report Summary**

On 09/19/2024 at approximately 13:42 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC OVERACKER 29-04 pad.
Location # 311653 in Garfield County Colorado.

Please refer to inspection 708902524 conducted on 12/11/2023 & inspection 708903439 conducted 04/01/2024, previous corrective action has been completed.

Location is within High Priority/Density/NSO/Black Bear Habitat areas.

Location is approximately 142 yards from a drainage that contributes to the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

Dual lease - Shared facilities with location # 335139

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.			
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	Chemical tanks			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-9377			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Possible staining in secondary containment, however at this time unable to determine extent due to recent rainfall & small amount of stormwater accumulation in secondary containment.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Pig station - pipe rail fence			

Corrective Action:		Date:	
Type	OTHER		
Comment:	Summit Midstream meter house - pipe rail fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	OVERACKER 29-03D & OVERACKER 29-04B bradenhead lines connected to ECD.		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Taylor plugs located on all bradenhead, bradenhead valves are accessible. OVERACKER 29-03D & OVERACKER 29-04B bradenhead lines connected to ECD. Please refer to document #'s 402872172 & 402872233		
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	OTHER	STEEL AST		,	

Comment:	Tanks equipped with telemetry					
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)	250 bbls					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent				
Comment:	Centralized containment					
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type	Ignitor/Combustor					
Comment:	OVERACKER 29-03D & OVERACKER 29-04B bradenhead lines connected to ECD. Please refer to document #'s 402872172 & 402872233					
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	285306	Type:	WELL	API Number:	045-12424	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	285308	Type:	WELL	API Number:	045-12422	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	288105	Type:	WELL	API Number:	045-13157	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	288106	Type:	WELL	API Number:	045-13156	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Gravel				Sparse to none in sections
Gravel						Sparse to none in areas
				Material Handling And Spill Prevention		Chemical tank containments
		Culverts				
Compaction						Small amount of light compaction
		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Housekeeping for comments	smelserw	09/22/2024
Dual lease - Shared facilities with location # 335139		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904641	Inspection 708904640 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6716513
708904642	Inspection 708904640 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6716514