

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2024

Submitted Date:

09/13/2024

Document Number:

707801096

## FIELD INSPECTION FORM

 Loc ID: 316758  
 Inspector Name: Ramsey, Scott  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 ECMC Operator Number: 6720  
 Name of Operator: ROBERT L BAYLESS PRODUCER LLC  
 Address: 621 17TH ST STE 2300  
 City: DENVER State: CO Zip: 80293
**Findings:**

- 10 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Thomas, John	505-326-2659	jthomas@rlbayless.com	
Trujillo, Helen		notices@rlbayless.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232649	WELL	SI	01/01/2024	GW	107-06063	DRY CREEK UNIT 3-22	PR

**General Comment:**[ECMC Inspection Report Summary](#)

On Monday 8/19/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Bayless Dry Creek 3-22, at Location # 316758 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Battery signage lacking information
2. Tank labeling lacking information
3. No evidence of bird protection on heat treater
4. Some stained material
5. 1 anchor not marked properly

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labeling lacking information		
Corrective Action:	Provide proper labeling	Date:	10/18/2024
Type	BATTERY		
Comment:	Battery signage lacking information		
Corrective Action:	Provide proper signage	Date:	10/18/2024

<b>Emergency Contact Number:</b>			
Comment:	<input type="text" value="(505)327-0880/911"/>		Date:
Corrective Action:	<input type="text"/>		<input type="text"/>

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Some stained material		
Corrective Action:	Remove stained material, dispose of properly and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.	Date:	10/18/2024
Type	OTHER		
Comment:	No evidence of bird protection on heat treater		
Corrective Action:	Provide proper bird protection or proof of protection	Date:	10/18/2024

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:	Possibly 2		
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:	1 anchor not marked properly		
Corrective Action:	Mark or remove anchor		Date: 10/18/2024
Type: Ancillary equipment	# 1		
Comment:	Propane tank		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 232649 Type: WELL API Number: 107-06063 Status: SI Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Gravel						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403923100	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709348">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709348</a>
707801099	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709342">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709342</a>