

<b>FORM INSP</b> <small>Rev X/20</small>	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>08/28/2024</u> Submitted Date: <u>09/16/2024</u> Document Number: <u>707801098</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID 316782    Inspector Name: Ramsey, Scott    On-Site Inspection     2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10469  
 Name of Operator: ENERGY INVESTMENTS INC  
 Address: 2110 W LONG SKY DRIVE  
 City: ST GEORGE    State: UT    Zip: 84770

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Miller, Ann	(303) 912-2188	ann@energy-investments.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273763	WELL	PR	04/01/2023	OW	107-06222	WOLF MOUNTAIN 15-2-7-87	PR

**General Comment:**

ECMC Inspection Report Summary  
 On Wednesday 8/27/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Energy investments Wolf Mountain #15-2-7-87, at Location # 316756 in Route county Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.  
 During this inspection the following possible compliance issues were observed:

1. Weeds around equipment
2. Random staining though out location
3. Standing oil at well head
4. Possible tank leaking

Refer to photograph of observed compliance issue.  
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Some labeling becoming illegible		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	10/18/2024

Emergency Contact Number:

Comment: (303)531-5816/911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Staining around equipment and standing oil at well head		
Corrective Action:	Remove stained material, dispose of properly and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.	Date:	10/18/2024
Type	WEEDS		
Comment:	Weeds around equipment		
Corrective Action:	Remove weeds and eliminate potential risk of fire from fired equipment	Date:	10/18/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

Type: Bird Protectors	# 5		corrective date
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 4	
Comment:	Propane tanks	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Chemical tank in plastic containment	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Generator	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Concrete	Adequate	Walls Sufficient	Base Sufficient	
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					

Other (Capacity) 210 BBLs	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Concrete	Adequate	Walls Sufficient	Base Sufficient		
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				
				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				
				Date:

**Inspected Facilities**

Facility ID: 273763 Type: WELL API Number: 107-06222 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No storm water BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403923102	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709349">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709349</a>
707801101	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709344">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709344</a>