

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2024

Submitted Date:

09/16/2024

Document Number:

714201643**FIELD INSPECTION FORM**Loc ID 318480 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
,		cogcc@kpk.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241373	WELL	SI	11/01/2021	OW	123-09162	MARVIN E. SCHUTT UNIT 1	TA

General Comment:

THIS IS AN INSPECTION IN RESPONSE TO COMPLAINT DOC#: 403901254 and A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 702403227.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	overgrown vegetation surrounding pumpjack and ancillary equipment. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/16/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	241373	Type:	WELL	API Number:	123-09162	Status:	SI	Insp. Status:	TA	
Idle Well										
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED				
Comment:		<div>Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.</div>								
Corrective Action:		<div>Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.</div>						Date:		04/26/2024
BradenHead										
Date of Last Brhd Test:		01/22/2024		Annual Brhd Completed?		Yes				
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:				
		End Surf Csg Pressure:		0						
Comment:		<div></div>								
Corrective Action:		<div></div>						Date:		

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.110800 Long: -104.888500Wind: Light Speed: 5 (mph) Direction From: E Weather: Clear Temperature: 84 (F)Assisting Staff Brittani Santistevan Camera #: _____☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
12:15	PM	12:30	PM	Wellhead(s)

Comment: It appears to be no venting from pumpjack. see attached video

Corrective Action: _____ Date: _____

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground, On Wednesday, September 11, 2024 at approximately 12:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at MARVIN E. SCHUTT UNIT #1 (KP Kauffman Company Inc.), at location ID: 318480 in WELD COUNTY, Colorado. While there, I observed a TA pumpjack. During this inspection the following possible compliance issues were observed:</p> <p>1. It appears to be overgrown vegetation surrounding the ancillary equipment and pumpjack fencing. Comply with Rule 606. (Corrective Action Date: October 16, 2024) See attached photo #2-5.</p> <p>2. It appears the well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. (Corrective Action Date: April 26, 2024)</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	09/16/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403921947	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6708423
714201646	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6708413
714201647	Video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6708414
714201648	Video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6708415