

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2024

Submitted Date:

09/23/2024

Document Number:

715200980

**FIELD INSPECTION FORM**Loc ID 321046 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kelly, George		envexbaca@aol.com	
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205855	WELL	PR	07/01/2019	GW	009-06270	HANCOCK M 1	PR

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Dirt road through farm ground			
Corrective Action				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Stickers on tank are peeling off and need replaced			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 10/23/2024
Type	WELLHEAD			
Comment:	Lease sign by water tank is faded			
Corrective Action:	Install sign to comply with Rule 605.d.			Date: 10/23/2024
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Maintain weeds around welhead and cathodic rectifier			
Corrective Action:	Comply with Rule 606			Date: 10/23/2024
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	OTHER			
Comment:	Pipe cage around cathodic rectifier			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Prime Mover	# 1			
Comment:	Arrow gas engine			
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	Solar powered cathodic rectifier and gas scrubber			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	American unit. Horsehead removed at time of inspection			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter run is 100' to the west of wellhead. Meter shed is leaning and needs to be fixed		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	Open Top		37.362420,-102.238500	
Comment:	Fiberglass open top water tank. Tank is empty at time of inspection					
Corrective Action:					Date:	

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Berms around tank need maintenance				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 10/23/2024

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	205855	Type:	WELL	API Number:	009-06270	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing gas production. Last reported production was 11/1/23. Casing valve is unable to close (see photo #4)								
Corrective Action:	Submit reports as per Rule 207.  Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.							Date:	10/23/2024
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200990	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6717481">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6717481</a>