

Inspection Photos

September 18th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 325820

Inspection Document #: 714001233

La Plata County, CO

Township: SENW 25 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huber Burkett 1-25
Location ID: 325820



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-07031

Inspection Photos
Location Name: Huber Burkett 1-25
Location ID: 325820



Photo 2. View of the northern interim reclamation area facing northwest.

Inspection Photos
Location Name: Huber Burkett 1-25
Location ID: 325820



Photo 3. Impacted surface material corrective action identified in the previous inspection doc #690204344 has been addressed/resolved.

Inspection Photos

Location Name: Huber Burkett 1-25

Location ID: 325820



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Wildlife BMP at chemical tank secondary containment is damaged and no longer functioning, maintenance is needed.

API #: 067-07031

Inspection Photos

Location Name: Huber Burkett 1-25

Location ID: 325820



Photo 5. View of flowering Muks thistle and Mullein observed in the southern interim reclamation area.

Inspection Photos
Location Name: Huber Burkett 1-25
Location ID: 325820



Photo 6. Reference area comprised of Gambel oak, Pine and Squirrel tail.

