

Inspection Photos

September 18th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326512

Inspection Document #: 714001235

La Plata County, CO

Township: SWNE 25 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huber Burkett 3-25
Location ID: 326512



9/18/24
+37.275721,-107.693096
154° SE



9/18/24
+37.275962,-107.693156
181° S

Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Huber Burkett 3-25
Location ID: 326512



Photo 2. View of the eastern interim reclamation area facing north.

Inspection Photos

Location Name: Huber Burkett 3-25

Location ID: 326512



9/18/24
+37.275450,-107.692912
131° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Patch of flowering Musk thistle observed in the southern interim reclamation area.

API #: 067-08229

Inspection Photos
Location Name: Huber Burkett 3-25
Location ID: 326512



Inspection Photos
Location Name: Huber Burkett 3-25
Location ID: 326512



Photo 5. Reference area comprised of Gambel oak, Pine and Squirrel tail.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08229