

Interim Reclamation and Stormwater Inspection

Date: 9/16/24

Operator: PDC Energy Inc - 69175

Location ID: 484682

Inspection Document #: 713900995

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Trippett 3N66W3 1-48
Location ID: 484682



Photo 1. The photo was taken at the well location facing Northeast. The photo illustrates the Operator location sign and forms mailbox.



Photo 2. The photo was taken at the well location facing East. The photo illustrates the topsoil stockpile and other areas of disturbance outside of the drilling pad are dominated by Russian thistle, Kochia and puncturvine.

Inspection Photos
Location Name: Trippett 3N66W3 1-48
Location ID: 484682



Photo 3. The photo was taken at the well location facing East. Refer to the comment for photo 2.



Photo 4. The photo was taken at the well location facing North. The photo illustrates puncturvine dominates areas of previously bare soil around the sediment trap on the South side of the location.

Inspection Photos
Location Name: Trippett 3N66W3 1-48
Location ID: 484682



ECMC
358° N
9/16/24, 4:05 PM

Photo 5. The photo was taken at the well location facing North.
Refer to the comment for photo 4.



ECMC
4° N
9/16/24, 4:08 PM

Photo 6. The photo was taken at the well location facing North.
Refer to the comment for photo 2.

Inspection Photos
Location Name: Trippett 3N66W3 1-48
Location ID: 484682



Photo 7. The photo was taken at the well location facing North. Refer to the comment for photo 2.



Photo 8. The photo was taken at the well location facing East. The photo illustrates wildlife burrowing through the berm near the controlled drain as well as puncturevine growing throughout.

Inspection Photos
Location Name: Trippett 3N66W3 1-48
Location ID: 484682



Photo 9. The photo was taken at the well location facing West. Refer to the comment for photo 2.



Photo 10. The photo was taken at the well location facing North. The photo illustrates stained soil around the wells.

Inspection Photos
Location Name: Trippett 3N66W3 1-48
Location ID: 484682



ECMC
27° NE
9/16/24, 4:18 PM



ECMC
184° S
9/16/24, 4:21 PM

Photo 10. The photo was taken at the well location facing Northeast. The photo illustrates stained soil underneath a containment tarp.

Note - It is likely the tarp has more damage and is leaking more fluids onto the pad.

Photo 11. The photo was taken at the well location facing South. Refer to the comment for photo 2.

Inspection Photos
Location Name: Trippett 3N66W3 1-48
Location ID: 484682



Photo 12. The photo was taken at the well location facing Northeast. Refer to the comment for photo 2.

Note - The tracking along the sediment trap slopes are tracked the incorrect direction.