

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2024

Submitted Date:

09/17/2024

Document Number:

698602330**FIELD INSPECTION FORM**Loc ID 303519 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253225	WELL	PR	03/11/1985	GW	125-07102	JONES 2	PR

General Comment:

Routine Inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign on tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign posted on Gas Meter Run Shed. Sign is unreadable and needs to be replaced.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on meter shed at well location.

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Separator/Gas Meter Shed.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods removed from wellbore. Tubing appears to be in the wellbore. Tubing valve open. Casing valve not connected.		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:	Gas Meter Run. Chart in Meter Box dated 8-1-24. Meter Calibration/Test Log dated 7-25-24. Well Inlet Valve open. Gas Outlet Valve open.	
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:	Inside shed.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV FIBERGLASS		40.044910,-102.328560
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Erosion channel has cut through the berm wall.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 10/18/2024

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	253225	Type:	WELL	API Number:	125-07102	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Tubing appears to be in wellbore. Tubing valve open. Casing valve not connected. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 7/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Pass	Material Handling And Spill Prevention	Fail	Erosion channel through tank berm wall.
Gravel	Fail					

Comment: Erosion channels at meter shed and produced water tank. Channels are carrying sediment down grade from location. See attached inspection photos.

Identified in previous 4/2/2024 Inspection document number 698601933. Inspection photos attached. Corrective action not performed or insufficient to prevent recurrence. Corrective action date remains the same to document period of non-compliance. Erosion issues at this location were previously identified in FIR's completed 1/13/2022 document number 688311855 and 2/14/2022 document number 688312138.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C**

Date: 04/19/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403925203	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711398
698602363	04022024 FIR Document 698601933 Inspection Photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711393
698602364	08302024 FIR Document 698602330 Inspection Photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711394