

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2024

Submitted Date:

09/17/2024

Document Number:

708302750

**FIELD INSPECTION FORM**

Loc ID 447695 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
9 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447698	WELL	PR	01/09/2018	GW	045-23310	BMC B 12D-18-07-95	PR
447706	WELL	PR	03/24/2018	GW	045-23318	BMC B 23D-18-07-95	PR
447707	WELL	PR	03/27/2018	GW	045-23319	BMC B 14A-18-07-95	PR
447708	WELL	PR	02/02/2018	GW	045-23320	BMC B 23B-18-07-95	PR
447709	WELL	PR	03/28/2018	GW	045-23321	BMC B 23A-18-07-95	PR
447710	WELL	PR	04/11/2018	GW	045-23322	BMC B 13B-18-07-95	PR
447711	WELL	PR	04/01/2023	GW	045-23323	BMC B 13C-18-07-95	PR
447712	WELL	PR	02/22/2018	GW	045-23324	BMC B 23C-18-07-95	PR
447713	WELL	PR	02/23/2018	GW	045-23325	BMC B 13D-18-07-95	PR
447715	WELL	PR	01/19/2018	GW	045-23327	BMC B 13A-18-07-95	PR
447716	WELL	PR	01/14/2018	GW	045-23328	BMC B 22D-18-07-95	PR
449469	WELL	PR	12/10/2017	GW	045-23477	BMC B 32B-13-07-96	PR
449470	WELL	PR	11/29/2017	GW	045-23478	BMC B 42A-13-07-96	PR
449474	WELL	PR	11/23/2017	GW	045-23479	BMC B 41C-13-07-96	PR
449475	WELL	PR	12/30/2017	GW	045-23480	BMC B 42C-13-07-96	PR
449478	WELL	PR	02/10/2018	GW	045-23481	BMC B 43B-13-07-96	PR
449479	WELL	PR	11/27/2017	GW	045-23482	BMC B 32A-13-07-96	PR
449480	WELL	PR	05/01/2023	GW	045-23483	BMC B 43A-13-07-96	PR
449482	WELL	PR	01/07/2018	GW	045-23484	BMC B 42D-13-07-96	PR
449484	WELL	PR	12/21/2017	GW	045-23485	BMC B 32C-13-07-96	PR
449485	WELL	PR	02/28/2018	GW	045-23486	BMC B 43C-13-07-96	PR

449487	WELL	PR	05/01/2023	GW	045-23487	BMC B 42B-13-07-96	PR
449489	WELL	PR	11/28/2017	GW	045-23488	BMC B 41B-13-07-96	PR
449490	WELL	PR	04/01/2023	GW	045-23489	BMC B 41D-13-07-96	PR

**General Comment:**

[CECMC Inspection Report Summary](#)

On 9/11/2024 at approximately 14:35, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, BMC B PAD at Location ID #447695 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Stored equipment in tank battery containment

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/(970)285-9377		
Corrective Action:		Date:	_____

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Stored equipment (load hoses) in tank battery containment.		
Corrective Action:	Remove stored equipment to comply with Rule 606.	Date:	09/24/2024

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 20		
Comment:			

Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	<a href="#">Summit Midstream</a>		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 20		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">CataDyne</a>		
Corrective Action:		Date:	
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	<a href="#">Chemical tanks</a>		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: <u>447698</u>	Type: <u>WELL</u>	API Number: <u>045-23310</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>447706</u>	Type: <u>WELL</u>	API Number: <u>045-23318</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>447707</u>	Type: <u>WELL</u>	API Number: <u>045-23319</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>447708</u>	Type: <u>WELL</u>	API Number: <u>045-23320</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>447709</u>	Type: <u>WELL</u>	API Number: <u>045-23321</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>447710</u>	Type: <u>WELL</u>	API Number: <u>045-23322</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>447711</u>	Type: <u>WELL</u>	API Number: <u>045-23323</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>447712</u>	Type: <u>WELL</u>	API Number: <u>045-23324</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447713 Type: WELL API Number: 045-23325 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447715 Type: WELL API Number: 045-23327 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447716 Type: WELL API Number: 045-23328 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449469 Type: WELL API Number: 045-23477 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449470 Type: WELL API Number: 045-23478 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449474 Type: WELL API Number: 045-23479 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449475 Type: WELL API Number: 045-23480 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	449478	Type:	WELL
API Number:	045-23481	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	449479	Type:	WELL
API Number:	045-23482	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	449480	Type:	WELL
API Number:	045-23483	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	449482	Type:	WELL
API Number:	045-23484	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	449484	Type:	WELL
API Number:	045-23485	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	449485	Type:	WELL
API Number:	045-23486	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	449487	Type:	WELL
API Number:	045-23487	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Facility ID: 449489 Type: WELL API Number: 045-23488 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449490 Type: WELL API Number: 045-23489 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Gravel				
				Material Handling And Spill Prevention		
Berms						
Gravel						
		Compaction				

Comment: [Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403925292	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711549">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711549</a>
708302751	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711545">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711545</a>