

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2024

Submitted Date:

09/17/2024

Document Number:

715200962

**FIELD INSPECTION FORM**Loc ID 321664 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 17180

Name of Operator: CITATION OIL &amp; GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207720	WELL	PR	03/01/2022	OW	017-06655	ARAPAHOE UNIT 139 (43-27)	PR

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Stickers on chemical tanks		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil around prime mover		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	09/24/2024

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Prime Mover	# 1		
Comment:	Ford 300-6 cylinder motor		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	American 320		

Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Cathodic rectifier, day drum, gas scrubber, chemical drum w/containment		
Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	207720	Type:	WELL	API Number:	017-06655	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (AU 139, 140, 141, 144, 145 [IJ], 180 [TA]) 4250' NW @ 38.812810/-102.101720								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403925135	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711329">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711329</a>
715200968	location photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711312">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711312</a>