

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2024

Submitted Date:

09/17/2024

Document Number:

717700500

FIELD INSPECTION FORM

Loc ID 317706 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10528
Name of Operator: ARCH OIL & GAS LLC
Address: 16400 DALLAS PARKWAY SUITE 305
City: DALLAS State: TX Zip: 75248

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Collins, Kilian		kilian.collins@state.co.us	
HEASLIP, TRACY	(239) 404-0929	theaslip@archog.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239823	WELL	SI	09/01/2020	GW	123-07611	ELMER KAUFMAN 2	SI

General Comment:

[This is a routine inspection](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Safety Fence around the open hole needs to be repaired.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	09/27/2024

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 239823 Type: WELL API Number: 123-07611 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well appears to be plugged, Cut & Capped
Form 42(PA) #403746950
Form 6(N) #403733934 No Form 6(S) on file
Form 27(I) #403763248

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday September 16, 2024, at approximately 8:30 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Well: Elmer Kaufman 2 Operator: Arch Oil & Gas LLC API: 05-123-07611 County: Weld</p> <p>During the inspection, The following possible compliance issues were identified: Fencing: Safety Fence around the open hole needs to be repaired. Comply with the fencing requirements per the 1002a rules A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	09/17/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403924193	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6710443
717700501	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6710436