

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad

Location ID: 335504



Photo # 1687 From entrance to location



Photo # 1688 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad

Location ID: 335504



Photo # 1689 Location



Photo # 1690 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad

Location ID: 335504



Photo # 1691 Location



Photo # 1692 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad

Location ID: 335504



Photo # 1693 Location



Photo # 1694 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad

Location ID: 335504



Photo # 1695 Location



Photo # 1696 RWF 532-25 wellhead sign weathered, cracking & peeling/some info is starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad

Location ID: 335504




Photo # 1697 Debris



Photo # 1698 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad

Location ID: 335504



Photo # 1699 Barbed wire fence around location needs maintenance/wildlife hazard (S/SW area of location)



Photo # 1700 Barbed wire fence around location needs maintenance/wildlife hazard (S/SW area of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad

Location ID: 335504



Photo # 1701 Barbed wire fence around location needs maintenance/wildlife hazard (S/SW area of location)