

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2024

Submitted Date:

09/18/2024

Document Number:

696206238**FIELD INSPECTION FORM**Loc ID 323800 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.com	All NW inspections
Olson, Andrew		AndrewOlson@chevron.com	All NW inspections
Bittner, Dawn [Populus]		stephaniebittner@chevron.com	All NW inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210835	WELL	PA	08/08/2014	CBM	045-06593	CHEVRON SHALE 1-25A CHEVRON	RI

General Comment:

On 9/17/2024, Western Reclamation Work Lead Trujillo conducted a Final Reclamation inspection at Chevron Usa Inc's CHEVRON SHALE #1-25A CHEVRON location in Garfield County, Colorado.

This inspection is a follow-up to Inspection #696205961 to document compliance with the following compliance issues:
-1004 Final Reclamation

It was observed that the Location remains out of compliance with 1004 Reclamation requirements.

Refer to the Reclamation section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Inspected Facilities									
Facility ID:	210835	Type:	WELL	API Number:	045-06593	Status:	PA	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment _____

Topsoil on Location has not been replaced, is predominantly bare, and has not been protected pursuant to Rule 1002.c.

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control **Fail**

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present In Process Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: See "COGCC Comments" at the end of this report.

Corrective Action: _____ Date _____

Corrective Action per Inspection #696205961:

Comply with Rule 1004.a and conduct reclamation on the Location and access road including, but not limited to, recontouring/regrading, replacement of topsoil and revegetation activities. Ensure erosion controls are implemented to stabilize the seeded soil pursuant to Rule 1002.f. Comply with Rule 1004.e and 606.c and perform ongoing weed management; Oil and Gas Locations will be kept free of all Undesirable Plant Species.

Continue to monitor and manage the Location; ongoing stormwater and weed management required until the site receives a passing final reclamation inspection.

Overall Final Reclamation

FailWell Release on Active Location ☐Multi-Well Location ☐**ECMC Comments**

Comment	User	Date
Form 6(s) #400682542 states well was P&Ad 8/8/2014.	trujilloam	09/18/2024
Operator submitted Form 4 #401407509 stating "Final Reclamation was complete".		
Inspection Nos. 692400010 and 696205961 observed that final reclamation of the Location has not been performed in accordance with 1004 Rules:		
-Location and access road have not been recontoured/regraded, and reclaimed in accordance with Rule 1004.a. Cut and fill slopes remain apparent; topsoil remains bare and stockpiled on the north, west and southeastern ends of the Location, and has not been replaced. Undesirable Plant Species (Mullein) have continued to establish and spread on the Location and access road.		
Inspections required Operator to comply with 1004 Rules.		
It was observed in this inspection that work to reclaim the Location in accordance with 1004 Rules has not been performed, and the Location remains out of compliance. Noxious weeds (Mullein) remain evident on the Location, however weed management efforts do appear to have been previously performed; ongoing weed monitoring/management required until Location receives a passing final reclamation inspection.		
Corrective actions have not been completed, and remain applicable.		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403926349	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6712485
696206239	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6712479