

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2024

Submitted Date:

09/25/2024

Document Number:

713601457**FIELD INSPECTION FORM**Loc ID 307696 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10351Name of Operator: WAPITI OPERATING LLCAddress: 1251 LUMPKIN RDCity: HOUSTON State: TX Zip: 77043**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name       | Phone                     | Email                         | Comment |
|--------------------|---------------------------|-------------------------------|---------|
| Madison, Randy     | 575-445-6706/575-420-1120 | rmadison@wapitienergy.com     |         |
| Mattorano, Michael | 575-445-6704/505-652-0416 | mmattorano@wapitienergy.com   |         |
| Middlebrook, Sonny | 575-445-6724/575-445-8610 | smiddlebrook@wapitienergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 89234       | WELL | PR     | 09/15/1999  | CBM        | 071-06814 | VPR C 5       | RI          |

**General Comment:**

This is a reclamation inspection at the VPR C #5 wellsite.

Reclamation - Storm Water - Pit

Storm Water:

|  |                 |  |                       |               |                          |                  |
|--|-----------------|--|-----------------------|---------------|--------------------------|------------------|
| Loc Erosion BMPs   | BMP Maintenance | Lease Road Erosion BMPs  | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment          |
|  |                 |  |                       |               |                          |                  |
| Comment:   |                 | There is erosion occurring on the access road that needs to be repaired and stabilized with BMP's such as gravel. This issue has previously been observed and needs to be properly stabilized. |                       |               |                          |                  |
| Corrective Action:   |                 | Install or repair required BMPs per Rule 1002.f.(2)C   |                       |               |                          | Date: 10/11/2024 |
| Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT |                 |  |                       |               |                          |                  |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

|              |                   |   |
|--------------|-------------------|---|
| Document Num | Description       | URL   |
| 713601458    | Inspection Photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6720408">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6720408</a> |