

Inspection Photos

Loc: 307766

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307766 | Date: 9/23/2024

Inspection Photos



Photo 2. There is an erosion channel at the northwest side of the location that needs to be repaired. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307766 | Date: 9/23/2024

Inspection Photos



Photo 3. There are other erosion channels along the cut slope that have not been repaired.



Inspection Photos



Photo 4. There is an erosion channel at the northeast side of the location that needs to be repaired. Previous CA was not completed.

